

SUPPLEMENT TO H-58-11-ASAM-06 AN/ALQ-144 WIRING HARNESS



FIG 1: AN/ALQ-144 Countermeasures Set J1 and J2 Cables secured to "Dummy" receptacles.

The following Warning will be added to a future update to TM 11-1520-248-23, Task 7-4-3:

WARNING

Secure Excess Wiring Harness (J1 and J2) slack to prevent contact with aircraft Tail Rotor Drive Shaft."