
## Addendum to H-58-11-AMAM-16 Torquemeter Support Duplex Bearings

Torquemeter Support with Paint Stripped from Bearing



## Closer view of Duplex Bearing with Paint Stripped



## Addendum to H-58-11-AMAM-16 Torquemeter Support Duplex Bearings

## Tools used for stripping the paint



- Stripper 7, 8010-00-181-7568, this product used with the tools shown to the left, will remove the paint around the entire torquemeter support in approximately 20 minutes.
- Thinner, Polyurethane Thinner, 8010-00-181-8080, this product will quickly clean (less than 20 minutes) the torquemeter support to provide good paint adhesion.
- The curing time for painting will vary based on environmental conditions.